


A mirror is used here to show exhaust leakage from a gas fired water heater (the mirror fogs up from the water vapor condensating on it.)



Termites cause more damage in the US than fires. This main house beam was completely eaten out.)

This is knob and tube wiring. It was the first wiring installed when houses first got electricity. Most insurance companies will not insure homes that have active knob and tube wiring.

